

M60EX065


1/1

Surinkimo schema
Схема сборки
Assembling scheme

Reikalingi įrankiai:

Инструменты для сборки:

Requiring tools:




1



x8

2



x8

3



x8

4



x8

5



x4

6





x2

7







x8

I




Assembling back


II




U2N100/U2C100
H=754



U3N100/U23100
H=1120



U4N100/U4C100
H=1508



U5N100/U5C100
H=1874