









Assembly instruction : desk range B (N)



4x (A)  47 mm M8 x 20 554786	6x (B)  M6 x 16 500182	8 x (C)  PH 6.3 x 19 500254	2x (D)  PH 4.5 x 20 582330	2x (E) (bei N-Serie)  582330	Tools:   SW 4
---	---	--	---	--	--


2x (1)  (li) (1) (re) (1) B-Fuss li /re 115243 N-Fuss li /re 115244	1x (2)  KA08-2 668 mm KA12-2 1068 mm KA16-2 1468 mm KA18-2 1668 mm KA20-2 1868 mm	1x (3) PL08 / PL12 / PL16 / PL19/ PL2E  PL**
---	---	---

1




je 2x

(A)



4x **(A)**



47 mm
M8 x 20

554786

